## Oil Field Environmental Incident Summary

Incident: 20150901151225 Date/Time of Notice: 09/01/2015 15:12 Responsible Party: PETRO-HUNT, L.L.C. Well Operator: PETRO-HUNT, L.L.C. Well Name: ANNA OSADCHUK 2 Field Name: TREE TOP Well File #: 7249 **Date Incident: 9/1/2015** Time Incident: 10:30 Facility ID Number: **BILLINGS** Rng: 100 Sec: 14 Qtr: County: Twp: 142 **Location Description:** Submitted By: Derek Enderud Received By: Contact Person: Derek Enderud **PO BOX 935** BISMARCK, ND 58502 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident Equipment Failure Release Contained in Dike Yes - Within Dike Reported to NRC: No **Spilled** Units Recovered Units Followup **Units** Oil 100 **Barrels** 100 **Brine Barrels** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation:

None.

Areal Extent:

| Potential | <b>Environmental</b> | Impacts: |
|-----------|----------------------|----------|
| Potentiai | Environmentai        | impacts  |

None, everything contained within dike.

## Action Taken or Planned:

Vac truck was called and starting removing fluid immediately.

Wastes Disposal Location:

Agencies Involved:

## **Updates**

Date: 9/1/2015 Status: Reviewed; O&G Lead Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Release, due to an equipment failure, remained on location according to the report. NDIC retains oversight.